RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA





3439 Brookside Road, Suite 108 Stockton, CA 95219 Tel: 209-475-5100 Fax: 209-475-5102

www.colliers.com

Gregory O'Leary, SIOR Senior Vice President (209) 475-5108 Direct g.oleary@colliers.com CA License No. 00924479 Mike Goldstein, SIOR

Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com CA License No. 01319234 John Steinbuch, SIOR

Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107

RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA

Property Specifications:

Address: 1815 Navy Drive, Stockton, CA 95206

Zoning: IG - General Industrial

General Description: Rail served manufacturing and warehouse facility

Building Specifications:

Square Footage: Approximately 252,237 square feet

Site Area: Approximately 12.10 acres (APN: 163-300-06)

Construction Type: Poured-in-place concrete

Loading Doors: Grade level and dock high

Parking: Fenced separate area for automobile parking

containing approximately 60 spaces.

Rail: Burlington Northern & Santa Fe Railroad Company

Electrical: 3,000+ Amp; 480V; 3-Phase

Warehouse Lighting: Sodium Vapor and Metal Halide

Fire Sprinklers: Calc System

Column Spacing: Buildings 3 & 4 - Clear Span

Building 5 - Column Spacing 24' x 90'

Price: \$4,500,000

Building Specifications (continued):

Yard Area: Various areas in rear (north side) of warehouse

Sewer: City of Stockton - 48" truck line in Navy Drive

Water: California Water Service - 8", 12" and 20"

Services in Navy Drive

Storm: On-site

Gas & Electric: Pacific, Gas & Electric

General Information: Located in the California State Enterprise Zone

Building	Square Feet	Clear Height	Grade Level	Dock High	Comments
1	68,077 SF	15′8″ - 18′	2	1	Rail served
2	13,500	15′8″	2	0	
3	35,100	28′	2	0	Clear span
4	35,100	28′	2	0	Clear span
5	95,769	26′	5	3	24' x 90' column spacing
Out Bldg 1	1,500	-	1	-	Flammable Storage
Out Bldg 2	3,200	-	1	-	Hazardous Storage

BROKERS



3439 Brookside Road, Suite 108 Stockton, CA 95219 Tel: 209-475-5100 Fax: 209-475-5102

www.colliers.com


EXCLUSIVE LISTING

Gregory O'Leary, SIOR
Senior Vice President
(209) 475-5108 Direct
g.oleary@colliers.com
CA License No. 00924479

Mike Goldstein, SIOR

Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com CA License No. 01319234 John Steinbuch, SIOR Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107

RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA





3439 Brookside Road, Suite 108 Stockton, CA 95219 Tel: 209-475-5100

Fax: 209-475-5102 www.colliers.com

EXCLUSIVE LISTING BROKERS

Gregory O'Leary, SIOR

Senior Vice President (209) 475-5108 Direct g.oleary@colliers.com CA License No. 00924479

Mike Goldstein, SIOR Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com

CA License No. 01319234

John Steinbuch, SIOR Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107

RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA











3439 Brookside Road, Suite 108 Stockton, CA 95219 Tel: 209-475-5100

Fax: 209-475-5102 www.colliers.com

EXCLUSIVE

Gregory O'Leary, SIOR Senior Vice President (209) 475-5108 Direct q.oleary@colliers.com CA License No. 00924479


Mike Goldstein, SIOR

Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com CA License No. 01319234


John Steinbuch, SIOR

Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107

RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA









3439 Brookside Road, Suite 108 Stockton, CA 95219


Tel: 209-475-5100 Fax: 209-475-5102 www.colliers.com

EXCLUSIVE LISTING BROKERS

Gregory O'Leary, SIOR Senior Vice President

(209) 475-5108 Direct g.oleary@colliers.com CA License No. 00924479 Mike Goldstein, SIOR Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com CA License No. 01319234 John Steinbuch, SIOR Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107

RAIL SERVED MANUFACTURING/WAREHOUSE FACILITY APPROXIMATELY 252,237 SF ON 12.10± ACRES - STOCKTON, CA





3439 Brookside Road, Suite 108 Stockton, CA 95219

Tel: 209-475-5100 Fax: 209-475-5102 www.colliers.com

EXCLUSIVE LISTING BROKERS

Gregory O'Leary, SIOR

Senior Vice President (209) 475-5108 Direct g.oleary@colliers.com CA License No. 00924479

Mike Goldstein, SIOR

Managing Partner (209) 475-5106 Direct michael.goldstein@colliers.com CA License No. 01319234

John Steinbuch, SIOR

Senior Vice President (925) 227-6212 Direct john.steinbuch@colliers.com CA License No. 00687107